

Appendix B – Photographs



1



2



3



4



5



6



7



8

Beckett's Creek – views downstream (1) and upstream (2, 3) of mainstem as visible from Regional Road 174; views are partially obscured by trees and shrubs. Photo 2 shows evidence of slope failure on the southeast bank. Views downstream (4) and upstream (5) from Old Montréal Road. Steep embankments and gully erosion evident upstream (6) and downstream (7, 8) along Old Montréal Road.

Photos 1-5 taken September 7, 2018. Photos 6-8 taken November 1, 2021.



9



10



11



12



13



14



15

Becketts' Creek – views downstream (9) and upstream (10) from Wilhaven Drive. Views downstream (11) and upstream (12) from French Hill Road. Views downstream (13) and upstream (14) of Birchgrove Road. Photo 15 shows a low flow assessment being carried out at Birchgrove Road 560 m south of Etienne Road.

Photos 9-12 taken September 7, 2018. Photos 13-14 taken November 1, 2021. Photo 15 taken September 13, 2016.



16



17



18



19



20



21



22

Beckett's Creek – views downstream (16) and upstream (17) from Etienne Road.

Beckett's Creek Tributaries – views downstream (18, 19) and upstream (20, 21) of various tributaries along Emmett Road. Photos 19, 21 and 22 show examples of culverts in need of rehabilitation.

All photos taken November 1, 2021.



23




24



25



26



27



28

Beckett's Creek Tributaries – views downstream (23) and upstream (24) from Birchgrove Road north of Etienne Road. Views downstream (25) and across fields (26) from Sarsfield Road south of Beaton Road. Significant woodland visible on the horizon (26). Views downstream (27) and upstream (28) from Canaan Road, south of Oakwood Drive, showing very minimal flows.

Photos 23-24 taken November 1, 2021. All other photos taken September 7, 2018.



29



30



31



32



33



34



35

Municipal Drains – view of D. LeGault Drain downstream of Birchgrove Road showing submerged culvert (29). View of Beckett Creek Drain downstream (30) along Canaan Road north of Etienne Road. Culvert is perched, making fish passage difficult, and is rusted through in places (31). View of Beckett Creek Drain upstream from Etienne Road (32). View of Mercier Branch Drain north of Innes Road to the west (33) and east (34). Portion of drain has since been cleaned out (34). View of culvert, showing stagnant conditions, along Theodule Vachon Drain at Dunning Road (35).

Photo 29 taken May 6, 2014. Photo 35 taken September 12, 2016. All other photos taken September 7, 2018.



36



37



38



39



40



41

Catchment A – views downstream from Old Montréal Road (36) and upstream from Pierrette Drive (37) within Hillside Estates.

Catchment C – view downstream from Kinsella Drive south of Golightly Terrace (38). View upstream from Kinsella Drive east of Byrnes Terrace (39). View downstream from Old Montréal Road (40).

Photo 41 shows a view of the Ottawa River, from Regional Road 174, towards the western extent of the Baie Lafontaine Provincially Significant Wetland.

Photo 38 taken May 6, 2014. Photo 41 taken September 7, 2018. All other photos taken November 1, 2021.



42



43



44



45



46



47

Wildlife – Photo 42 shows a muskrat grazing by Beckett's Creek downstream of Old Montréal Road. Photo 43 shows an eastern kingbird near Beckett's Creek at Wilhaven Drive; yellow-rumped warbler, tree swallow, mallard and robin were also observed. Photo 44 shows a ruffed grouse observed along Lough Drive. Photo 45 shows a monarch butterfly, a species of special concern, on a willow shrub near Beckett Creek Drain. Photo 46 shows a northern leopard frog near Beckett's Creek along French Hill Road. Photo 47 shows a school of minnows in a pool of a small tributary to Beckett's Creek downstream of McTeer Road. In smaller tributaries, pools often provide refuge for small fish, frogs and other aquatic life during low-flow periods. Photos 42-44 were taken on May 6, 2014. Photos 45-47 were taken on September 7, 2018.