




SLOUGH



DEEP-SEATED ROTATIONAL FAILURE



EARTH FLOW SLIDE (PER MITCHELL AND MARKELL, 1974)



AFTER KARROW (1972)

TYPES OF SLOPE FAILURES

FIGURE 7

